

Appendix 12

Area Monitoring

Figure 1 – Location of VUV Area Monitors

Figure 2 – Location of X-ray Area Monitors

Figure 3 – Area Monitoring for 2nd floor offices – 1999 – 2002

Figure 4 – Area Monitoring for VUV Ring Locations – 1999 – 2002

Figure 5 – Area Monitoring for X-ray Ring Locations – 1999 – 2002

Figure 6 - Distribution of Annual TEDE for Monitored Individuals

Figure 1 - Location of VUV Area Monitors




Figure 2
Location of X-ray Area Monitors



Figure 3

Area Monitoring for 2nd floor offices – 1999 – 2002
Adjusted for Occupancy of 2000 hours/year




Figure 4

Area Monitoring for VUV Ring Locations – 1999 – 2002
Adjusted for Occupancy of 2000 hours/year




Figure 5

Area Monitoring for X-ray Ring Locations – 1999 – 2002
Adjusted for Occupancy of 2000 hours/year




Figure 6

Distribution of Annual TEDE for Monitored Individuals

